Advanced Gas Metal Arc Welding (WLDG 2447)

Credit: 4 semester credit hours (2 hours lecture 8 Hour Lab)



Prerequisite/Co-requisite: WLDG 2413

Course Description

Advanced topics in GMAW welding, including welding in various positions and directions

Required Textbook and Materials

- 1. Modern Welding by Althouse, Turnquist, Bowditch 2013
 - a. ISBN number is 978-1-60525-795-2
- 2. Personal Tool List (approximately \$150-\$250).
 - 1. Hood
 - 2. Welders cap
 - 3. Shade 10 or 11 lens
 - 4. Clear lens (10)
 - 5. Long sleeve 100% cotton shirt or leather sleeves or leather jacket
 - 6. Long 100% cotton work pants (jeans)
 - 7. High top leather boots (steel toe)
 - 8. Leather gloves
 - 9. Chipping hammer
 - 10. Wire brush
 - 11. Safety glasses
 - 12. Cutting goggles or glasses (shade 5)
 - 13. Measuring tape
 - 14. Tip cleaner
 - 15. 12" combination square
 - 16. Pliers

Students will not be allowed in class without the proper equipment and clothing

Course Objectives

Upon completion of this course, the student will be able to:

- 1. Demonstrate proficiency with GMAW in various welding positions on pipe.
- 2. Describe safety rule and equipment used in GMAW.
- 3. Describe the effects of welding parameters in GMAW.
- 4. Weld various joint designs and diagnose welding problems and perform visual inspections.

Course Outline

1. Define safety procedures when using GMAW equipment

- i. Discuss and perform safety procedures when setting up the GMAW welding station
- ii. Discuss and perform safety procedures for handling high pressure shielding gas cylinders
- iii. Discuss and practice proper personal protective equipment while using GAMW

2. Define welding parameters of GMAW

- i. Discuss and set wire speed on GMAW machine
- ii. Discuss and set voltage on GMAW machine
- iii. Discuss and select the proper shielding gas
- iv. Discuss how the weld position affects the welding parameters of GMAW

3. Demonstrate proficiency in GMAW welding in various positions

- i. GMAW carbon steel pipe in 1G position
- ii. GMAW carbon steel pipe in 2G position
- iii. GMAW carbon steel pipe in 5G position
- iv. GMAW carbon steel pipe in 6G position

4. Test and diagnose various joint designs and welds

- i. Discuss and perform visual test of welds
- ii. Discuss and perform both nondestructive and destructive test
- iii. Discuss and identify flaws and defects in weld
- iv. Discuss proper joint design

Grade Scale

90 - 100	A
80 - 89	В
70 - 79	C
60 - 69	D
0 - 59	F

Course Evaluation

Final grades will be calculated according to the following criteria:

Assignments 30% TEST 70%

Late Penalties will be assessed on all work turned in late. 5 points per day.

Average a grade on all test and assignments of at least 70%.

Course Requirements

- 1. Attend class regularly.
- 2. Demonstrate proficiency with the pipe beveling machine and track torch
- 3. Demonstrate proficiency with GMAW in various welding positions on pipe.
- 4. Weld various joint designs and diagnose welding problems and perform visual inspections.

Attendance Policy

- I. Students are allowed to miss two days without penalty; each additional day will result in the student's grade being dropped by a letter grade.
 - Example: 2 days absent = If student has an A average no penalty
 - 3 days absent = A drops to a B
 - 4 days absent = B drops to a C
 - 5 days absent = C drops to a D (student must retake class)
 - 6 days absent = D drops to a F (student must retake class)
- II. Absences are counted for unexcused, excused and coming to class late.
- III. 3 tardies = 1 absence
 - A. Tardy- arriving within 15 minutes after class begins or leaving before the end of class.
 - B. More than 15 minutes late you will be counted absent.
 - C. If you go to sleep in class you will be counted absent.
- IV. **Excused absences.** Only given to allow students to make up missed work.
 - A. Will be given for documented Injury or Illness. Doctor's excuse required showing proof. Will count toward total days missed.
 - B. Will be given for documented Death in immediate family. Will count toward total days missed.
 - C. Approved LIT school functions; E.g. SkillsUSA, SGA etc. Will not count toward total days missed
 - D. It is the student's responsibility to obtain from the instructor any handouts or assignments for classes missed. Lectures will not be repeated.
- V. If you wish to drop, you are responsible for the drop process. I will not initiate the drop, no matter how many absences or zeroes you have; that is, if you stop coming to class and do not drop, you will earn an "F" in the course. Students are only allowed to drop 6 times in their college career.

Course Policies

- 1. No electronic devices of any kind (cell phones, I-pod, headphone, etc.) will be tolerated in the classrooms or labs. If you are seen using any electronic device you will be asked to leave the class for the day.
- 2. No food or drink will be allowed in the classroom.
- 3. No derogatory or foul language will be tolerated.
- 4. We have a zero tolerance policy for sexual harassment.
- 5. We have a zero tolerance policy of racial or ethnic discrimination.
- 6. Be considerate of others in the classroom.

Disabilities Statement

The Americans with Disabilities Act of 1992 and Section 504 of the Rehabilitation Act of 1973 are federal anti-discrimination statutes that provide comprehensive civil rights for persons with disabilities. Among other things, these statutes require that all students with documented disabilities be guaranteed a learning environment that provides for reasonable accommodations for their disabilities. If you believe you have a disability requiring an accommodation, please contact the Special Populations Coordinator at (409) 880-1737 or visit the office in Student Services, Cecil Beeson Building.

Course Schedule

Week	Topic	Reference
1-2	Course introduction and policies Shop orientation and safety procedures	Syllabi
	Cutting torch safety and procedures Measuring and Lay-out tools Use the Oxyfuel torch to cut metal Set up GMAW/FCAW station Weld Fillet weld in various position and test • LECTURE/LAB	Instructor Demonstration/ Supervision
3-6	Use track torch to cut beveled plates GMAW/FCAW weld Vee Groove welds in all positions and test • LECTURE/LAB	Instructor Demonstration/ Supervision
7-8	Use pipe beveling machine to bevel pipe GMAW/FCAW weld pipe in 1G (roll out) position and test • LECTURE/LAB	Instructor Demonstration/ Supervision
9-10	Use pipe beveling machine to bevel pipe GMAW/FCAW weld pipe in 2G position • LECTURE/LAB	Instructor Demonstration/ Supervision
11-13	Use pipe beveling machine to bevel pipe GMAW/FCAW weld pipe in 5G position • LECTURE/LAB	Instructor Demonstration/ Supervision
14-16	Use pipe beveling machine to bevel pipe GMAW/FCAW weld pipe in 6G position • LECTURE/LAB	Instructor Demonstration/ Supervision